
ACCESSORY FITMENT

Product		Isuzu Nudge bar		
Part no.	1	1600062T, BS-1600062, BS-XRIDER-62		
Q.	60 Minutes	Models :ALL		
		Page 1 of 1		
		Date :02/09/2020		

DIAGRAM



Kit content:

·	Qty	Description		Qty	Description
Α	4	M10 x 30 sets	J	8	M8 x 22 x 1.6 flat washers
В	6	M8 x 30 sets	K	2	M8 hex nuts
С	2	M10 x 40 x 1.25 pitch sets	L	2	U-bolts
D	2	M10 x 30 x 1.25 pitch sets	М	2	Nudge bar bottom mount bracket
Ε	6	M8 spring washers	N	2	Chassis mount bracket
F	12	M10 spring washers	0	2	Nudge bar front mount bracket
G	6	M10 Hex nuts	Р	2	Spacer
Н	12	M10 x 30 x 2 Flat washers			
I	2	M10 x 40 x 3 flat washers			

Additional equipment/Material needed for fitment :

Qty	Socket set	Qty	Spanner set
	Screw driver set		
	Torque wrench		

Precautions during fitment:

Avoid contact with sharp objects when removing packaging

Directions for use:

Bar must be secure and not hindering the bumper of the vehicle before signing off fitment.

Page 2 of 6

Fitment Instruction:

Isuzu nudge

Visual / Graphic Illustration		Description/Method
Simulated crumple zone	1	Mount bracket N to the outside of the crumple using the fastners provided. Keep the bracket loose.
N	Fas	ters needed per side to mount bracket N
	1	0.0010 (=)
	2	M10 x 30 x 2 Flat Washers (H)
	2	M10 spring washers (F) M10 hex nuts (G)
Actual crumple zone		

Page 3 of 6

Fitment Instruction:

Isuzu nudge

	Cton #	Description / Mathed		
Visual / Graphic Illustration	Step#	Description/Method		
	2	Mount Bracket M to the under of the Chassis the fine thread bolts provided.		
	Fas	sters needed per side to mount bracket M		
	1	M10 x 40 x 1.25 pitch sets (C)		
Spacer to	1	M10 x 30 x 1.25 pitch sets (D) M10 x 30 x 2 Flat Washers (H)		
be	2	M10 Spring Washers (F)		
inserted P				

Page 4 of 6

Fitment Instruction:

Isuzu Nudge

	1 0 "		
Visual / Graphic Illustration	Step#	Description/Method	
N O	3	Attach bracket O to bracket M and N as shown in the picture.	
	Fasters needed per side to mount bracket O to M		
	1	M10 x 30 Set (A)	
	1	M10 Hex Nut (G)	
	2		
0	1	M10 Spring Washers (F)	
M	Faste	rs needed per side to mount bracket O to N M8 x 30 Set (B) M8 Hex nut (K) M8 x 22 x 1.6 Flat washer (J) M8 Spring washer (E)	

Page 5 of 6

Fitment Instruction:

Isuzu Nudge

Viewal / Graphia Illustration	Step#	Description/Method
Visual / Graphic Illustration	4	Mount Bracket O to the bar as shown in PIC 1 and mount bracket M to the bar as shown in PIC 2
PIC 1	Fasters n	eeded per side to mount bracket O to the Bar
	2	M8 x 30 Set (B)
	2	M8 Spring washers (E)
	2	M8 x 22 x 1.6 Flat washers (J)
	Fasters n	eeded per side to mount bracket M to the Bar
	1	M10 x 30 Set (A)
	1	M10 spring washer (F)
	1	M10 x 40 x 3 flat washer (I)
M PIC 2		

Page 6 of 6

Final step

Make sure bar is centralised and tighten all fasteners to specified torque. M8= 22Nm , M10= 42Nm , M6= 9Nm.

